



# BAT

PIN NO.	SYMBOL
1	Vss
2	Vdd



1	Lcd Type	FSC LCD+快速液晶
2	Viewing Direction	12H
3	Drive Method	1/1 duty ; 1/1bias
4	Polsrizer Mode	Negative black Transmissive
5	Operating Voltage	3.0V
6	Operating Temperature	0°C ~50°C
7	Storage Temperature	-30°C ~80°C

The non-specified tolerance of dimension is  $\pm 0.3\text{mm}$ .

SCALE:	1/1	UNIT:	mm	華凌光電(常熟)有限公司 WINSTAR DISPLAY CO.
REV:	0			
				MODEL
APPROVE				WDO0048-CFB-#00
CHECK				TITLE
				LCM DRAWING
DRAW	曹波 05/25/09'			DWG NO.
				90515001